



---

# Landsat 7 Anomaly Status

*presented by*


**Jim Irons**

**Landsat Data Continuity Mission Project Scientist  
NASA Goddard Space Center**

*at*

**LP DAAC Science Advisory Panel Meeting  
USGS Headquarters, Reston, VA  
September 10, 2003**


# EDC Archived – Launch to Date



Daytime full scenes archived at EDC  
29 June 1999 through 30 June 2003

1 - 12   13 - 27   28 - 44   45 - 70   71 - 91

# International Cooperator Network




Argentina  
China  
Thailand

Australia (2)  
ESA (4)  
South Africa

Brazil  
Indonesia

Canada (2)  
Japan (3)\*

# IGS Acquired – Launch to Date



Daytime full scenes scheduled for IGS stations  
29 June 1999 through 30 June 2003

1 - 15    16 - 36    37 - 58    59 - 77    78 - 90

# Landsat-7 ETM+ Scan Line Corrector Anomaly

---

- **What happened**
- **What is its impact on the data**
- **What is the prognosis/status of resolution**
  - **Timeline**
  - **Options**


# What Happened

---


- **Normal motion of the scan line corrector (SLC) stopped at 21:44:05 GMT on 5/31/2003**
- **SLC compensates for forward motion of spacecraft to provide parallel forward and reverse scans and full ground coverage**

# Impact of Stopped SLC

---




With SLC




Without SLC

# Scan Gap Dimensions



## Impact of Stopped SLC (near center of image)



SLC

NO  
SLC

No  
SLC  
With  
interp

# SLC Anomaly Response - Initial Actions

---

- **Anomaly Review Team (ART) formed**
- **SLC powered off on June 6th (DOY 157-21:22:08 GMT)**
- **Data acquisitions reduced to thermal maintenance and anomaly investigation imaging**
  - **Duty cycle increased from 2.8% to 11% on July 14 (16% nominal duty cycle)**
- **Post-anomaly data not currently orderable**

# SLC Anomaly Investigation

---

- **Electrical and Mechanical Fault Trees generated and analyzed--no purely electrical failure explained anomaly**
- **Electronic Simulation (SPICE) model generated -- produced results consistent with observed telemetry when “stuck” mechanism assumed**
- **On-orbit results indicate mirror has moved some since event, i.e., not completely frozen**
- **Engineering SLC model analyzed**
- **After much analysis, deliberation, and review, the ART recommended a test with power sent to the SLC from the redundant “B-side” electronics**
  - **Approved by USGS Director Groat with concurrence of NASA AA Asrar**

# “Side B” Test Results

---

- **No Joy**
  - ETM+ operations were switched to the B-side electronics beginning last Thurs., Sept. 04
  - Power from the B-side electronics was sent to the SLC for a period of less than three minutes last Sun., Sept. 07
  - Power from the B-side failed to restore SLC operability; no mirror oscillation observed
  - Telemetry from the SLC motor tachometer indicates that the mechanism and motor are jammed or stuck

# Plans

---

- **Return to A-side electronics and resume full ETM+ acquisition schedule with SLC turned off**
- **Modify product generation software in EDC systems to produce Level 1 products with SLC-off data**
- **Work with USGS and DOI to fund continuing Landsat 7 operations in light of lost revenue for International Ground Stations and reduced ETM+ data sales**
- **Explore other possible actions to restore SLC function**
  - **Additional efforts are unlikely**